

Re X4-A9.1

13 July 66

Comments

①

The 0-80 key chart has seriously biased a lot of the thinking, in an undesirable direction ---

① Does not allow for a significantly larger NL key.

② Puts the active surface of the shift in too close to core.

③ Crowds in other function keys to central core.

② ASCII Pairings are incompatible with established typewriter practice. For the future this is a cost/conformity problem.

① Keys 6, 10-16, 35, 54-55 are affected. (Not including comma ~~and period~~ and period keys.)

Eleven Keys